

SAFCO/IBB



# RUBBING DETECTION IN A SYNTHESIS GAS COMPRESSOR

NOV 2015

By: Dr. Chinmaya Kar & Mr. Waleed J. Al-Sallom

A decorative graphic at the bottom of the page consisting of two thick, wavy, overlapping lines. The top line is yellow and the bottom line is blue, both curving upwards from left to right.

CHEMISTRY THAT MATTERS™


## PROBLEM STATEMENT

Large shaft vibration of

- 52µm persisting for last 1 year at HP DE in one proximity probe, and
- 40µm persisting for last 1 year at Turbine LP End for both proximity probes

No. 1

## HISTORICAL FAILURE



No. 2

## HISTORY OF THE IBB SYNTHESIS GAS COMPRESSOR

### 2011 TA

- Slight sludge observed on seal housings at oil seal assemblies of both ends .
- Both ends of inner and outer seal rings are found scoring - replaced.
- NDE tilting pad seal clearance found out of tolerance.
- Parallel misalignment observed and corrected

### May 2012 Shut down:

- Gear coupling failure at HP-Turbine side as oil supply nozzle is not directed towards lubricating zone
- Seal rings have been scored and HP DE side oil seals were replaced
- Parallel and angular misalignment found and corrected
- Thrust bearing of turbine replaced

### Oct 2012 Shut down

- Wiping of journal bearing bottom pads on both DE & NDE noticed.
- Sludge noticed on the inner seal rings on both DE & NDE.
- Parallel and angular misalignment found and corrected


### Summary of the maintenance history:

- A repeated parallel and angular misalignment is observed – Coupling can be the reason as evident in the coupling failure in May 2012
- Scoring of seal rings with sludge – One of the main reason is misalignment

No. 3


## OVERALL SHAFT VIBRATION IN MARCH 2014

- The LP side of steam turbine vibration shows a large amplitude of 42µm pp in both the direction
- One of the HP side probe of the steam turbine shows 53µm pp




No. 4

## VIBRATION ANALYSIS – ORBIT PLOTS



No. 5

## VIBRATION ANALYSIS – SPECTRUM PLOTS




No. 6


## SHAFT VIBRATION AT LP COMPRESSOR

- The LP compressor's NDE probes indicate normal vibration
- There is a reverse precession observed (may be detrimental in future with large fatigue of the shaft) – this may be the reason of probe and key phasor placement as well

Full Spectrum



Filtered 1X Orbit plot




No. 7


## SHAFT VIBRATION AT LP COMPRESSOR

- The LP compressor's DE probes indicate normal vibration
- There are a number of 1X, 2X, 3X components shows either looseness or rubbing
  - The mild looseness / rubbing indicates that it may be in the journal / seal / coupling
- Though the orbit plot is very irregular, doesn't show rubbing (impact – with straight lines) – may be an effect of steam turbine's LP side vibration

Full Spectrum



Orbit plot



No. 8





## SHAFT VIBRATION AT STEAM TURBINE

- The Steam turbine's LP Side probes indicate large vibration of 42µm pp in both the direction
- There are 1X, 2X, 3X components and also sub-harmonic component (near rotor natural frequency of 4000rpm) - either looseness or rubbing at bearing / seal / coupling
- The orbit plot is very irregular with some impact and straight lines and hence shows some mild rubbing

Half Spectrum

Orbit plot




No. 9

## SHAFT VIBRATION AT STEAM TURBINE

- The Steam turbine's HP Side probes indicate normal vibration
- However, large sub-harmonic components (particularly at exciting the rotor natural frequency) is a concern
  - The sub-harmonic component even showing an amplitude of 5µm which is very large


Half Spectrum



No. 10

## BODE PLOTS

- The Bode plot reveals large unbalance only at turbine HP side end as seen in the trend below
  - The amplitude increases with speed and phase between the probes is nearly 90°
- The other Bode plot have
  - Either large amplitude for some RPM range and then decreases with speed
  - Or have less amplitude




No. 11


## SHAFT VIBRATION AT HP COMPRESSOR

- The HP Compressor's DE Side probes indicate large vibration of 53μm pp in one direction (7608B)
- There are a number of 1X, 2X, 3X components shows either looseness or rubbing
- The orbit plot is very irregular with some impact and straight lines and hence shows some mild rubbing

Half Spectrum



Orbit plot



No. 12

## FIELD OBSERVATIONS: RUBBING AT STEAM TURBINE




No. 13

سابک  
sabic

## FIELD OBSERVATIONS: RUN-OUT OF STEAM TURBINE ROTOR

### FINAL DIMENSIONS & RUN OUT REPORT



Dimensions are in mm.

EXTENSION SHEET: -

$\alpha_i$	1	2	3	4	5	6	7
1.0	119.85	200.81	200.81	200.02	200.10	100.00	119.84

4 OUT SHEET:-

C	3	2	3	4	3	6	7	A	B	C	D	E	F	G	H	I	J	K
R	0.002	0.002	0.01	0.01	0.01	0.01	0.002	0.01	0.01	0.03	0.00	0.03	0.05	0.03	0.03	0.03	0.01	0.00

E	L	M	N	O	P	Q	R	S	T	U	V	W	X
E	6.03	6.63	0.03	0.03	6.63	0.03	6.63	0.03	6.03	6.03	6.63	0.0015	6.0015

works: Nil.

No. 14



## FIELD OBSERVATION: HP JOURNAL BEARING



No. 15

## CONCLUSION

There was evidence of rubbing from the vibration analysis

- Either at bearing or seals or gear coupling

Some looseness has also been noted

- The subsynchronous components and other 2X, 3X etc. components were found


There is an unbalance particularly near the turbine's HP side end only

- Only one side unbalance may indicate that the turbine's HP side coupling may have caused this effect as there is no unbalance effect in turbine's LP side

The sub-synchronous vibration with signs of rubbing may also be the effect of

- Either rubbing at the seal
- Or rubbing at the gear coupling

### Subsynchronous Vibration



No. 16

## CONCLUSION

---

Benefits of this analysis are

- Rubbing could be detected prior to Turnaround leading to
  - Proper planning in maintenance of the turbine
- FMEA analysis could determine all the probable faults and proper fault detection